## **INSPECTION REPORT**

| PERMIT NUMBER: | BP-15-00909 | OWNER'S NAME: | KANE |
|----------------|-------------|---------------|------|
|                |             |               |      |

DATE: 7/13/2016 Type: Exterior shear

TIME STARTED: 9:45 AM INSPECTOR: Justin Bennett

MAP NUMBER: 16-19-28050-0008

- 1. Corrections not complete
- 2. W2 @ Front bedroom has vertical seam not per shear schedule
- 3. Engineer Letter does not cover HD on Lvl 3 SE corner still needed
- 4. CS straps not nailed
- 5. A35 missing per shear schedule Lvl 3 south wall
- 6. DO NOT COVER

7. RE FEE

INSTRUCTIONS: DO NOT COVER/RE FEE/Complete above corrections/Re-Inspection

| NEXT INSPECTION:   | Re-Inspe | ection |       |                               |  |
|--|----------|--------|-------|-------------------------------|--|
|  |          |        |       |                               |  |
| RE-INSPECTION FEE  | DUE?     | □ NO   | ✓ YES | \$ _86.00                     |  |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION |          |        |       |                               |  |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL                  |          |        |       |                               |  |
|  | ADDRESS: |        | iust  | in.bennett @co.kittitas.wa.us |  |
| INSPECTION REQUEST LINE: 509-962-7694  |          |        |       |                               |  |
| http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx                |          |        |       |                               |  |

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506