## INICDECTION DEDOOT

INSPECTION REPORT			
PERMIT NUMBER:	BP-15-00910	OWNER'S NAME:	STROLE
DATE:	12/1/2016	TYPE:	Multiple (see notes)
TIME STARTED:	12:39 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-18-35050-0002		
<ol> <li>Mechanical rough in ok</li> <li>Attach bath fan duct to flapper at west end of house</li> <li>Fireplace not included in permit. Additional permitting required. Combustion air must be supplied to firebox. Chimney rough in ok</li> <li>Trusses ok</li> <li>Framing ok</li> <li>18" clearance to joists and 12" clearance to beams, from grade, must be maintained if not pressure treated</li> </ol>			
INSTRUCTIONS: Ok to insulate			
NEXT INSPECTION:	Insulation		
RE-INSPECTION FEE DUE? VES \$  IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE I	NSPECTOR AT THE FO essica.contratto @	

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506