INSPECTION REPORT

MOI ECHOIT KEI OKI			
PERMIT NUMBER:	BP-15-00922	OWNER'S NAME:	WT DEVELOPMENT
DATE:	2/3/2016	TYPE:	Frame-Plumb-Mech
TIME STARTED:	2:12 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-19-31077-0001		
 Plumbing not on test Stamped truss sheets not on site Rear patio footings not per plan Strap across plate break at beam pocket in front entry Verify length of truss screws used Double vapor barrier behind tub. Remove plastic sheeting Gas not at sufficient test pressure Install nail plates at plumbing lines Exhaust venting ok Insulate range vent Wall framing ok Headers and egress ok 			
INSTRUCTIONS: Complete above, ok to insulate walls NEXT INSPECTION: insulation and corrections			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506