## **INSPECTION REPORT**

INSPECTION REPORT			
PERMIT NUMBER:	BP-16-00078	OWNER'S NAME:	VANWURT
DATE:	6/2/2016	TYPE:	Slab plumbing
TIME STARTED:	1:01 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-22000-0012		
<ol> <li>DWV on stack</li> <li>Slab insulation</li> <li>Thickened foo</li> <li>Exterior upper</li> </ol>	n ok otings ok		
INSTRUCTIONS: OF	k to pour		
NEXT INSPECTION:	Shearwall		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
	ADDRESS:ie	essica.contratto @	co.kittitas.wa.us

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506