INSPECTION REPORT

PERMIT NUMBER:	BP-16-00134	OWNER'S NAME:	WEISBECK
DATE:	7/12/2016	TYPE:	Floor framing
TIME STARTED:	10:13 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-18-03011-0008		
Floor framing ok Obtain elevation certificate for floor framing			
INSTRUCTIONS: ok to sheath floor. Note that treated subfloor is needed for covered porch per plan note			
NEXT INSPECTION:	Shearwalls		
RE-INSPECTION FEE DUE? VES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694 http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			