INSPECTION REPORT						
PERMIT NUMBER:	BP-16-00268	OWNER'S NAME:	BARGE			
DATE:	6/16/2017	TYPE:	Framing			
TIME STARTED:	9:56 AM	INSPECTOR:	Jessica Contratto			
MAP NUMBER:	22-11-15052-0014					
 H20 at 20# Needs to be 50# minimum DWV not on test Exhaust duct not installed. Loft can be seen at final Laundry fan needs vented Range vent not roughed in. Will need to be in prior to cover. 6" pipe minimum Gas piping not on test Downstaairs bedroom window does not meet egress. Max height from floor is 44" to opening. Platform may be installed on floor to meet height requirements Roof insulation verified-ok 						
INSTRUCTIONS: Do Not Cover insulation. Complete above for re-inspect						
NEXT INSPECTION: Plumb/mech re-inspect						
	RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION						
	QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us					
	/ /DDI/F22	<u>coolea.commano</u>	CONTILLICATIVATA			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

PERMIT NUMBER:	BP-16-00268	OWNER'S NAME:	BARGE			
DATE:	6/16/2017	TYPE:	Framing			
TIME STARTED:	9:56 AM	INSPECTOR:	Jessica Contratto			
MAP NUMBER:	22-11-15052-0014					
Page 2						
INSTRUCTIONS: Do Not Cover insulation. Complete above for re-inspect						
INSTRUCTIONS: DO	o Not Cover insulation. Complete	above for re-inspi	501			
NEVT INSPECTION.						
NEXT INSPECTION: Plumb/mech re-inspect						
RE-INSPECTION FEE	DUE? NO YES		\$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION						
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL						
ADDRESS:iessica.contratto @co.kittitas.wa.us						
INSPECTION REQUEST LINE: 509-962-7694						

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

PERMIT NUMBER:	BP-16-00268	OWNER'S NAME:	BARGE			
DATE:	6/16/2017	TYPE:	Framing			
TIME STARTED:	9:56 AM	INSPECTOR:	Jessica Contratto			
MAP NUMBER:	22-11-15052-0014					
Page 3						
INSTRUCTIONS: Do Not Cover insulation. Complete above for re-inspect						
NEXT INSPECTION:	Plumb/mech re-inspect					
RE-INSPECTION FEE			\$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION						
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL						
	ADDRESS: j	essica.contratto @	co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694						

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

PERMIT NUMBER:	BP-16-00268	OWNER'S NAME:	BARGE			
DATE:	6/16/2017	TYPE:	Framing			
TIME STARTED:	9:56 AM	INSPECTOR:	Jessica Contratto			
MAP NUMBER:	22-11-15052-0014					
Page 4						
8. Walls are insulated. R-21 batt. Vapor barrier is required on exterior walls. Vapor barrier primer with rating of less than 1 perm acceptable alternative. Pro vide documentation 9. Framing ok 10. Upstairs fireplace venting not installed yet. Main fireplace not installed. Fireplace and chimneys will need to be seen prior to cover 11. Hydronics at 100#-ok						
INSTRUCTIONS: Do Not Cover insulation. Complete above for re-inspect						
NEXT INSPECTION: Plumb/mech re-inspect						
RE-INSPECTION FEE DUE? NO YES \$						
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION						
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>jessica.contratto</u> @co.kittitas.wa.us						
100000000000000000000000000000000000000						

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506