INSPECTION REPORT

PERMIT NUMBER:	BP-16-00276	OWNER'S NAME:	PAGE
DATE:	6/30/2016	TYPE:	Framing
TIME STARTED:	10:05 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-12040-0005		
 Post to truss connection per detail 1 and engineer note, using SDS screws as specified, not able to be verified Purlin connection at lean-to roof covered, unable to verify bolting at interior side Stamped trruss sheets not on site Truss gable bracing ok Other framing ok 			
INSTRUCTIONS: Ok to cover exterior and roof. Provide access to verify above corrections NEXT INSPECTION:			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506