



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00284

OWNER'S NAME: CURTIS

DATE: 8/26/2016

TYPE: Mechanical and plumbir

TIME STARTED: 4:52 PM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 18-19-31067-0003

1. Plumbing OK. Supply at 50#/15min. OK. DWV at 5#/15min. OK.
2. Exhaust/Supply Duct Work OK.
3. Floor Framing OK.
4. NOTE: Due to Small Nature of Remodel Framing Inspection Performed.
5. Trusses and Framing OK.
6. Breaks in Top Plate Closer than 2' in Multiple Locations. Strap Accordingly.

INSTRUCTIONS: OK to Insulate. MAke Corrections Above

NEXT INSPECTION: Insulation

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: jeremy.haberman @co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506