



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00303

OWNER'S NAME: MINERS CAMP

DATE: 8/5/2016

TYPE: Floor framing

TIME STARTED: 12:53 PM

INSPECTOR: Jessica Contratto

MAP NUMBER: 20-15-19000-0021

1. Floor framing is small area that can be seen at shear inspection. I gave approval for cover as floor joists were not installed yet. Vycor is installed under hangers

INSTRUCTIONS: Ok to cover

NEXT INSPECTION: Shearwalls

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: _____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506