



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00312

OWNER'S NAME: GOAD

DATE: 12/6/2016

TYPE: Framing

TIME STARTED: 12:11 PM

INSPECTOR: Justin Bennett

MAP NUMBER: 20-15-29051-0086

1. HD missing @ garage separation wall (clouded on A4)
2. Stair landing calls for (2) LVLs for second flr (clouded on A5)
3. Waterproof deck has soffit installed cannot confirm framing
4. WP Deck calls for (2) DTTZ to be installed
5. Interior shear walls in Great Rm not per detail 4/D3 - not continuously sheathed
6. Install A35's @ gable in bedroom 3
7. "V" Bracing not installed on south side of Great Rm per 5/D5
8. Deck lids and soffits are enclosed - need to verify framing
9. Knee braces not per 10/D5

INSTRUCTIONS: Complete above/Provide access to inspect soffit/deck framing

NEXT INSPECTION: Re-Inspection

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: justin.bennett @co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506