INSPECTION REPORT

PERMIT NUMBER:	BP-16-00327	OWNER'S NAME:	KNOLL
DATE:	7/19/2016	TYPE:	Framing
TIME STARTED:	12:28 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-15-07059-0007		
 All ledger attachments not per detail EDL. Anchors need to be 6" O.C. Detail DALL not complete 2 locations on back deck per plan HU48 hangers per plan at each side of front door (2) 2x8 used in lieu of 4x8 beams in 2 areas of front deck. Verify ok and stitch nailing requirements Beam 1-4 from back deck to existing not connected at house end. Supported by joists only. Provide positive connection to existing deck. Lateral attachment also required in this area Nail post caps. One by hot tub and one at front beam at entry 			
INSTRUCTIONS: Address above corrections. All corrections are highlighted in orange on approved plans onsite. Do not cover			
NEXT INSPECTION:	Re-inspect deck framing		
RE-INSPECTION FEE DUE? YES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE I ADDRESS: ic	NSPECTOR AT THE FOR essica.contratto	

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506