



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-16-00429

OWNER'S NAME: LAMBERT

DATE: 11/29/2016

TYPE: Exterior shear

TIME STARTED: 11:57 AM

INSPECTOR: Justin Bennett

MAP NUMBER: 19-14-01066-0001

1. NOTE: Underfloor Framing inspection performed
2. Provide engineer fix for sill plate attachment @ rear spread footing
3. Complete point load blocking
4. NOTE: Exterior Shear inspection also performed
5. Tighten up nailing @ P1-2 at front of house
6. Garage P2-3 not completed @ interior (to be seen later)
7. Provide engineer detail for flr to flr steps @ pony wall
8. NOTE: House walls were preassembled and sided at time of inspection (Armstrong House)

**INSTRUCTIONS:** Complete exterior shear corrections/Ok to cover exterior once complete/Re-Inspect underfloor for engineer detail

**NEXT INSPECTION:** Re-Inspection

**RE-INSPECTION FEE DUE?**



NO



YES

\$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  
ADDRESS: justin.bennett @co.kittitas.wa.us

**INSPECTION REQUEST LINE: 509-962-7694**

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506