



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00429

OWNER'S NAME: LAMBERT

DATE: 12/22/2016

TYPE: Framing

TIME STARTED: 12:37 PM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 19-14-01066-0001

1. Floor Framing Corrections OK.
2. Trusses OK.
3. Framing OK.
4. NOTE: Structure Was Inadvertently Insulated Prior to Framing Inspection. Insulation Was Removed in Places to Facilitate Framing Inspection.
5. NOTE: Due to Premature Insulation Installation, Insulation Inspection Performed at this Time Also.
6. Insulation OK.
7. NOTE: Sliding Glass Door Opens Onto Future Deck. Deck Will Require Permitting
8. NOTE: Crawlspace Exceeds 5' Height. Will Require 1/2 GWB Installation.
9. Fireplace Rough In OK.

INSTRUCTIONS: OK to Cover.

NEXT INSPECTION: Final

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: jeremy.haberman @co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506