INSPECTION REPORT

PERMIT NUMBER:	BP-16-00450	OWNER'S NAME:	GAGE
DATE:	4/28/2017	TYPE:	Floor framing
TIME STARTED:	1:28 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	17-19-04040-0015		
 Provide double top plate @ SE bump out - in progress Provide through pony wall access in all bump outs - clouded/in progress Complete blocking - in progress Provide crawl access per dwg 			
INSTRUCTIONS: Complete above/Once complete Ok to cover			
NEXT INSPECTION: Exterior Shear			
RE-INSPECTION FEE	DUE? V NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>justin.bennett</u> @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506