## **INSPECTION REPORT**

PERMIT NUMBER:	BP-16-00450	OWNER'S NAME:	GAGE
DATE:	7/7/2017	TYPE:	Framing
TIME STARTED:	8:47 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-04040-0015		
<ol> <li>Truss sheets do not match installed trusses</li> <li>Waste line not on test</li> <li>Detail 15/D2 in garage not complete</li> <li>Smoke/CO detector box missing at hall between bed #2 and #3</li> <li>Provide means to install gypsum board behind furnace</li> <li>Windows average .28, ok for energy credit chosen Efficient Envelope 1A.</li> <li>Insulate floor to R-38 to complete credit</li> <li>Gas not installed to residence. Efficient Water Heating credit chosen will need to be fulfilled by a heat pump water heater</li> <li>Exhaust duct ok</li> <li>Supply/Return duct ok. Duct in crawl not insulated</li> <li>Provide insulation and vapor barrier behind showers on exterior walls</li> </ol>			
INSTRUCTIONS: Provide waste line test, correction or engineer omission of 15/D2, and correct truss sheets. Do not insulate  NEXT INSPECTION: Re-inspect  RE-INSPECTION FEE DUE? NO YES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE I	NSPECTOR AT THE FO	

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506