## **INSPECTION REPORT**

INST ECTION KET OKT			
PERMIT NUMBER:	BP-16-00778	OWNER'S NAME:	TALISMAN
DATE:	7/10/2017	TYPE:	Insulation
TIME STARTED:	12:11 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	20-15-19056-0076		
<ol> <li>Firepalce Correction Not Addressed.</li> <li>Truss Bracing Correction Not Addressed.</li> <li>Holdown Missing at Rear Doorway. (Strap Presently Bent to the Ground.)</li> <li>Insulation OK. Batts w/PolyVisqueen Vapor Barrier.</li> <li>NOTE: Double Sided Interior Shear Needs to Be Seen Prior to Cover.</li> </ol>			
INSTRUCTIONS: OK to Install Plywood on Interio Shear Walls. DO NOT HANG DRYWALL OR COVER ANY OTHER WALLS OR CEILINGS.			
NEXT INSPECTION: REINSPECT			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: <u>jeremv.haberman</u> @co.kittitas.wa.us			
INCRECTION REQUIECT LINE FOR ACCURA			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506