INSPECTION REPORT

PERMIT NUMBER:	BP-17-00025	OWNER'S NAME:	MCDONALD
DATE:	6/12/2017	TYPE:	Mechanical and plumbir
TIME STARTED:	10:58 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-06093-0002		
 Gas at 30#-ok Exhaust duct ok Supply/return duct ok Check furnace drain termination at insulation inspection. Dead ends inside wall at this time Trusses ok Framing ok Heating duct in attic not insulated yet 			
INSTRUCTIONS: Ok to insulate			
NEXT INSPECTION: Insulation			
RE-INSPECTION FEE DUE? VIO YES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694			

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506