INSPECTION REPORT

BP-14-00428

PERMIT NUMBER:

OWNER'S NAME: BUSHNELL

DATE:		12/9/2014	TYPE:	Exterior shear
TIME STARTED:		11:19 AM	INSPECTOR:	Amber Green
MAP NUMBER:		17-19-13050-0004		
	1. Nails are undersized per the shearwall schedule.			
	2. Box nail sheathing to header at portal frame per detail at garage shearwa			
	3. Floor to floor straps at rear are called out to be MST37s.			
	4. Anchor bolt spacing is not per shearwall schedule at shearwalls.			
	5. Clips at rim per shearwall schedule.			
INSTRUCTIONS: Will need to complete #1 - #3 prior to approval for exterior cover. Can see #4 and #5 at framing inspection. Call for re-inspection, DO NOT COVER				
NEXT	INSPECTION:	Re-Shearwall		
RE-IN	SPECTION FEE	DUE? NO Y	'ES	\$
	IF REC	QUIRED, RE-INSPECTION FEES MUST	BE PAID PRIOR TO SC	HEDULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
			amber.green @co	o.kittitas.wa.us
		CTION REQUEST LINE: www.co.k 11 N. Ruby Street, Suite 2, Ellensburg		