## **INSPECTION REPORT**

PERMIT NUMBER: BP-14-00725 OWNER'S NAME: JACKSON

DATE:		5/29/2015	TYPE:	Re-inspection	
TIME STARTED:		2:55 PM	INSPECTOR:	Amber Green	
MAP NUMBER:		19-16-02000-0026			
	1. Waste @ 7#/15 mins - Ok				
	2. Supply @ 50#/15 mins - Ok				
	3. Windows within 24" horizontal of doorway are required to be tempered.				
	4. Main heating trunk line in attic to be insulated - see at later inspection.				
	5. Fireplaces not complete at this time, will see at next inspection.				
	6. Gas @ 15#/15 mins - Ok				
	7. Relocate exhaust termination @ left of entry a minimum of 3' from operable windows				
	8. Ok to insulate				
INSTRUCTIONS: Complete corrections listed/Ok to insulate once complete					
NEXT INSPECTION: Insulation					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iustin.bennett @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					