INSPECTION REPORT

TYPE:

OWNER'S NAME: LANDON

Framing

PERMIT NUMBER: BP-14-00731

DATE:

10/30/2015

TIME STARTED:	2:02 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	21-13-17050-0001		
1. Truss B	racing Missing On A1 thru A	.2 Trusses.	
	op Plate at Master Bedroom		
	equires (2) 2x10 in Two Loca		eers Approval.
INSTRUCTIONS: N	Make Corrections. OK to Ins	ulate.	
NEXT INSPECTION:	Insulation.		
RE-INSPECTION FEI	E DUE? V NO	YES	\$
IF REC	QUIRED, RE-INSPECTION FEES M	UST BE PAID PRIOR TO SCI	HEDULING A RE-INSPECTION
Q	UESTIONS? PLEASE CONTACT THE	INSPECTOR AT THE FOLL	OWING E-MAIL ADDRESS:
		ieremv.haberman @co	o.kittitas.wa.us
	CTION REQUEST LINE: www.c 11 N. Ruby Street, Suite 2, Ellensk		