INSPECTION REPORT

PERMIT NUMBER:	BP-14-00735	OWNER'S NAME:	EQUITY TRUST
DATE:	5/10/2016	TYPE:	Final
TIME STARTED:	1:56 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	20-15-29050-0074		
 Fan Not Hard Wired Fan Cannot be Controlled by Humidistat. Hand Rail on Stair Correction Not Completed. One Side Does Not have proper Sp acing.Right Hand Side When Ascending Does Not Meet Minimum Clearance. Photo In D rive. NOTE: Fan Manual Saved in 'T' Drive. NOTE: Photos Saved In Drive. 			
INSTRUCTIONS: Make Corrections Above.			
NEXT INSPECTION: Final			
RE-INSPECTION FEE	DUE? NO V YES		\$ 86.00
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>jeremy.haberman</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694			
http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			
411 N. Puby Stroot Suite 2. Ellensburg. WA 98926 A. Main Office Line: 509-962-7506			