INSPECTION REPORT

PERMIT NUMBER:	BP-15-00945	OWNER'S NAME:	BIRD CAPITAL MANAG
DATE:	6/26/2017	TYPE:	Floor framing
TIME STARTED:	1:42 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	20-15-19051-0031		
 NOTE: Exterior Piers Not Poured or Inspected At This Time. Inspection Require d Prior to Pouring. TJI Hangers In Contact With Pressure Treated Plate. Remove and ReInstall With VYCOR BARRIER. 			
INSTRUCTIONS: DO NOT SHEET FLOOR. Call For ReInspection When Ready.			
NEXT INSPECTION: Floor Framing.			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>jeremv.haberman</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694 http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			