INSPECTION REPORT

INSI ECHON KEI OKI			
PERMIT NUMBER:	BP-16-00078	OWNER'S NAME:	VAN WERT
DATE:	11/8/2016	TYPE:	Framing
TIME STARTED:	1:10 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-22000-0012		
1. Truss lateral bracing to be minimum of 2x4 lumber per truss install guidelines included with truss package 2. Gable end bracing per detail W032, page 15, not per plan. Is detail labeled incorrectly? Detail is W035 on page 15. All locations indicated on page 10 3. Outlookers not per plan:2x6 vertical at 24" oc, hangers at truss end, H1 at gable truss top chord. Currently 2x4 flat at 24". Note on page 10 4. Deck ties at rear deck require 2 DTT2Z ties per location			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:_

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iessica.contratto @co.kittitas.wa.us