INSPECTION REPORT

PERMIT NUMBER:	BP-16-00694	OWNER'S NAME:	MDJ CONTRACTORS
DATE:	12/27/2016	TYPE:	Exterior shear
TIME STARTED:	3:46 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	17-18-07060-0008		
 Install (4) MST fir to fir straps @ 2nd fir bump out (clouded) Provide engineer fix for (4) missing STHD straps right of entry (clouded) Provide engineer fix for BWP not width indicated on dwgs (clouded multiple lo cations) Provide 2" nailing @ 2nd fir bump out (2) locations 			
INSTRUCTIONS: Complete above/Re-Inspection NEXT INSPECTION: Re-Inspection RE-INSPECTION FEE DUE? V NO YES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS:iustin.bennett @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506