INSPECTION REPORT

INST ECTION NET ON			
PERMIT NUMBER:	BP-16-00777	OWNER'S NAME:	TALISMAN
DATE:	7/10/2017	TYPE:	Insulation
TIME STARTED:	12:18 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	20-15-19056-0075		
 Fireplace Correction Not Addressed. Truss Bracing Correction Not Addressed. Insulation Missing On Interior Party Wall. All Other Insulation OK. Batts w/P oly Visqueen Vapor Barrier. NOTE: Double Sided Interior Shear Needs to Be Seen Prior to Cover. 			
INSTRUCTIONS: OK to Install Plywood On Interior Shearwalls. DO NOT HANG DRYWALL OR COVER ANY OTHER WALLS OR CEILINGS.			
NEXT INSPECTION: REINSPECT.			
RE-INSPECTION FEE	DUE? NO YE	ES .	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT TH ADDRESS:	E INSPECTOR AT THE FO eremy.haberman @	
INSPECTION REQUEST LINE: 509-962-7694			
IINSPECTION REQUEST LINE: 303-302-7034			

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506