INSPECTION REPORT

PERMIT NUMBER:

BP-14-00261

OWNER'S NAME:

VAN DEVENTER

DATE:		9/2/2014	TYPE:	Re-inspection
TIME STARTED:		9:29 AM	INSPECTOR:	Amber Green
MAP NUMBER:		19-16-02000-0006		
	1. The engineer calls for (6) 16d nails at the rafter lap.			
	2. Engineer calls for 16 gauge strap over the top of the rafters at ridge.			
	3. Do not see fix for portal frame.			
	4. Fire sprinkler permit has still not been issued for this project.			
INSTRUCTIONS: Complete above corrections from engineer. Provide fix for portal frame. Obtain required permits before completing any further work. DO NOT COVER.				
		, , , , , , , , , , , , , , , , , , ,		
NEXT INSPECTION: RE-INSPECTION/FIRE SPRINKLER ROUGH-IN				
RE-INS	SPECTION FEE I	DUE? NO YES		\$ 65.00
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
amber.green @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 				