## **INSPECTION REPORT**

PERMIT NUMBER	<sup>:</sup> BP-14-00437	OWNER'S NAME:	HELGESON
DATE:	11/13/2014	TYPE:	Shearwalls
TIME STARTED:	9:22 AM	INSPECTOR:	Amber Green
MAP NUMBER:	19-15-08050-0004		
1. Nails	into the PT plate must b	e hot dipped ga	lvanized.
2. Nail shear panel at garage per 5/D1.			
3. Tighten up nailing an panel splice at bottom of gable trusses - 6" o.c.			
4. CS16	6 floor to floor straps mis	sing.	
5. All sill plate nailing to be 6" o.c.			
INSTRUCTIONS: Complete Above, Re-Call.			
NEXT INSPECTION	: Re-Shear		
RE-INSPECTION FE	E DUE? NO Y	ES	\$
IF RI	EQUIRED, RE-INSPECTION FEES MUST	BE PAID PRIOR TO SCHE	DULING A RE-INSPECTION
C	QUESTIONS? PLEASE CONTACT THE INS	SPECTOR AT THE FOLLOW	/ING E-MAIL ADDRESS:
amber.green @co.kittitas.wa.us			
	ECTION REQUEST LINE: <a href="www.co.ki">www.co.ki</a> 411 N. Ruby Street, Suite 2, Ellensburg		