INSPECTION REPORT

OWNER'S NAME: EMMERTON

TYPE: Shearwalls

PERMIT NUMBER: BP-15-00040

DATE:

5/20/2015

TIME STARTED:	10:27 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	19-16-24052-1203		
1. Straps a	re Ok		
	up edge nailing @ Shear	A (clouded on drawings)	
	up edge nailing @ Shear		
4. Portal Fr		,	
INSTRUCTIONS: N	lake corrections above/Ca	all for re inspection	
NEXT INSPECTION:	Re-Inspectiion		
RE-INSPECTION FEE	DUE? NO	YES	\$
IF REC	QUIRED, RE-INSPECTION FEES I	MUST BE PAID PRIOR TO SCH	EDULING A RE-INSPECTION
Ql	JESTIONS? PLEASE CONTACT T		
		iustin.bennett @co.	
	CTION REQUEST LINE: <u>www</u> 11 N. Ruby Street, Suite 2, Eller		uest.asp or 509-962-7694 ● fice Line: 509-962-7506
	,		