INSPECTION REPORT

OWNER'S NAME: EMMERTON

PERMIT NUMBER: BP-15-00040

DATE:	6/3/2015	TYPE:	Exterior shear
TIME STARTED:	9:59 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	19-16-24052-1203		
1. Waste on Stack - Ok			
2. Shear Corrections not complete			
3. Do Not Cover			
4. Re-inspection			
INSTRUCTIONS: Nail panel edges as indicated on shear schedule/Re Fee/Re-inspection			
NEXT INSPECTION: Re-inspection			
RE-INSPECTION FEE	DUE? NO V	ES	\$ <u>65.00</u>
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iustin_bennett @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			
111 III Haby Street, Saite 2, Enclisioning, W/130320 - Walli Office Encl. 303 302 7300			