INSPECTION REPORT

PERMIT NUMBER:	BP-15-00056	OWNER'S NAME:	LARSON
DATE:	5/12/2016	TYPE:	Re-inspection
TIME STARTED:	3:21 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-14-14050-0924		
 Correction 11 - HDU in master bath connected to anchor bolt - pending Correction 12 - Trellis framing not complete - pending Correction 14 - Fireplace not installed yet - pending Correction 17 - Truss repair - pending All other corrections Ok Ok to insulate 			
INSTRUCTIONS: Complete above corrections/Verify corrections @ Insulation/Ok to insulate once corrections are complete			
NEXT INSPECTION: Insulation			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: justin.bennett @co.kittitas.wa.us			
	,	I A O CHI I O CL	

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506