INSPECTION REPORT

PERMIT NUMBER:	BP-15-00165	OWNER'S NAME:	BV RESORT HOMES		
DATE:	5/31/2016	TYPE:	Framing		
TIME STARTED:	10:46 AM	INSPECTOR:	Justin Bennett		
MAP NUMBER:	20-15-19051-0032				
 A35's not complete per S3 Truss bracing not installed throughout Knee braces not installed per 3/S4 Install shear clips @ garage shear wall per 8/S2 Interior shear @ Bedroom 1 is not per 4/S4 - Provide engineer fix HVAC Duct main penetrates interior shear wall - Provide engineers approval Overframing @ Hall to Master not per details 1 & 2/S4 3 Ply Girder truss @ entry not installed per 8/S6 Provide truss manufacturer approval/fix for compromised truss above laundry Provide engineer approval/fix for 6x6 in lieu of 6x8 @ hallway to master Provide beam clips @ entry overhang per 6/S6 Remove header insulation for header inspection (4x12 typ window,door per S3) Provide engineer approval for BM R10 - Not glulam per schedule Provide engineer approval for BM S4 (R4) not per plans Provide Engineer approval for Garage Beam S1 notched to seat 4 ply girder truss INSTRUCTIONS: Provide accurate information for installed components/Re-Inspection (to be Complete Framing Inspection)					
NEXT INSPECTION:	Re-Inspection				
RE-INSPECTION FEE DUE? VES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
	QUESTIONS? PLEASE CONTACT THE I ADDRESS:	NSPECTOR AT THE FO iustin.bennett @			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

INSPECTION REPORT

TYPE:

PERMIT NUMBER: BP-15-00165

DATE:

5/31/2016

OWNER'S NAME: BV RESORT HOMES

Framing

TIME STARTED:	10:46 AM	INSPECTOR:	Justin Bennett		
MAP NUMBER:	20-15-19051-0032				
Page 2					
 16. NOTE: Framing Inspection not completed - Provide Engineer Approval for As-Bu ilt Condition 17. NOTE: Spoke with Jeff regarding inspection and he indicated accurate information was not on site 18. NOTE: Re-Inspection for Framing to be a complete Framing Inspection 					
INSTRUCTIONS: Provide accurate information for installed components/Re-Inspection (to be Complete Framing Inspection)					
NEXT INSPECTION: Re-Inspection					
RE-INSPECTION FEE DUE? VES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iustin.bennett</u> @co.kittitas.wa.us					
INSPECTION REQUEST LINE: 509-962-7694 http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					