

INSPECTION REPORT

PERMIT NUMBER: <u>BP-15-203</u>	OWNER'S NAME: STRINGFELLOW
DATE: 8/18/2015	TYPE: SHEARWIALLS
TIME STARTED: 10:50 am	INSPECTOR: HABERMAL
EXTERIOR SHEAR OF	
INCERTIONS.	
INSTRUCTIONS: 61/2 TO COVER	
NEXT INSPECTION: PLUMB MECH	
RE-INSPECTION FEE DUE? NO YES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION	
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:	
	@co.kittitas.wa.us
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 	