INSPECTION REPORT

PERMIT NUMBER: BP-15-00348 OWNER'S NAME: DRAIN

DATE:		11/17/2015	TYPE:	Exterior shear
TIME STARTED:		2:53 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:		16-19-02058-0003		
	_		_	
	NOTE: Remove House Wrap Paper For Nailing Verification.			
	2. BWP Not Adequate. Unable to Verify Anchor Bolts on 6 Foot Centers. Studs Must Be 16" O			
	Center. Panel Edges Must be Blocked & NAiled.			
	3. SW1 Not Adequate. Nailing Must be 3" On Center. Nails Into PT Plate Must be Galvanized.			
INSTRUCTIONS: Make Corrections Above. OK to Install Roofing.				
NEXT INSPECTION: Shear ReInspect.				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
ieremv.haberman @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 •				
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506				