INSPECTION REPORT

| PERMIT NUMBER: | | BP-15-00380 | OWNER'S NAME: | EDELWEISS CHALETS | |
|---|--|------------------|---------------|-------------------|--|
| DATE: | | 9/23/2015 | TYPE: | Framing | |
| TIME STARTED: | | 11:37 AM | INSPECTOR: | Jeremy Haberman | |
| MAP NUMBER: | | 22-11-09053-0212 | | | |
| | 1. All Retrofit/Replacement Framing on Laminated Girder #1 Complies with Engineering Provi | | | | |
| | ded By Kosnik Engineering | | | | |
| | 2. Beams Are Numbered Right to Left #1-#7 When Facing the Front of Structure From Outside | | | | |
| | 3. Provide Lamination Detail From Kosnik Engineering. | | | | |
| | 4. All Framing to be "Like for Like" With additional Clips Per Engineering. | | | | |
| | 5. NOTE: Photos Saved to "T" Drive. | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| INSTRUCTIONS: OK to Cover Girder #1. Proceed with Remaining Girder Installations. Call for | | | | | |
| Inspection as Needed. | | | | | |
| NEXT INSPECTION: Framing/Final | | | | | |
| RE-INSPECTION FEE DUE? YES \$ | | | | | |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: | | | | | |
| | ieremv.haberman @co.kittitas.wa.us | | | | |
| INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 | | | | | |