## **INSPECTION REPORT**

| PERMIT NUMBER:  | BP-15-00395      | OWNER'S NAME:      | THE PASS LLC    |
|---|------------------|--------------------|-----------------|
| DATE:   | 10/25/2016       | TYPE:              | Framing         |
| TIME STARTED:   | 1:10 PM          | INSPECTOR:         | Jeremy Haberman |
| MAP NUMBER:   | 22-11-04055-0013 |                    |                 |
| <ol> <li>All Prior Shear, Mechanical and Header Corrections OK.</li> <li>Framing OK.</li> <li>NOTE: Double Sided Shear Inspection Required Post Insulation Inspection.</li> <li>NOTE: Confirm Fire Marshall Approval of Sprinklers Prior to Cover.</li> <li>NOTE: Inspection of Gypsum Fire Walls Required Prior to Total Cover.</li> </ol> |                  |                    |                 |
| INSTRUCTIONS: OK to Insulate  NEXT INSPECTION: Insulation   |                  |                    |                 |
| Insulation  |                  |                    |                 |
| RE-INSPECTION FEE   |                  | DAID DDIOD TO SCUE | \$              |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION  |                  |                    |                 |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:  |                  |                    |                 |
|   |                  |                    |                 |

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506