INSPECTION REPORT

| PERMIT NUMBER: | BP-15-00792 | OWNER'S NAME: | KAPLAN |
|--|------------------|---------------|----------------|
| DATE: | 9/30/2016 | TYPE: | Framing |
| TIME STARTED: | 4:07 PM | INSPECTOR: | Justin Bennett |
| MAP NUMBER: | 20-15-13050-0002 | | |
| 1. Tighten up exterior nailing 2. NOTE: HD's to be verified @ framing | | | |
| | | | |
| | | | |
| INSTRUCTIONS: Complete above/Once complete Ok to cover exterior | | | |
| NEXT INSPECTION: Plumb/Mech | | | |
| RE-INSPECTION FEE DUE? NO YES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iustin.bennett</u> @co.kittitas.wa.us | | | |

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506