## **INSPECTION REPORT**

INST ECTION REFORM			
PERMIT NUMBER:	BP-16-00268	OWNER'S NAME:	BARGE
DATE:	11/14/2016	TYPE:	Exterior shear
TIME STARTED:	10:46 AM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	22-11-15052-0014		
<ol> <li>Front Gable Wall Sheeting Not Complete.</li> <li>Sides and Rear Wall Nailing OK. Holdowns Not Complete.</li> <li>NOTE: Permit Set Drawings Required To Be Onsite For All Inspections.</li> </ol>			
INSTRUCTIONS: Complete Shear Nailing and Holdown Installation Then Call For Shear ReInspect. OK to Install Building Wrap on Reaer and Side Walls.  NEXT INSPECTION: Shear Re Inspect			
Shear Re Inspect.			
RE-INSPECTION FEE DUE? VES \$  IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>ieremv.haberman</u> @co.kittitas.wa.us			
101000000000000000000000000000000000000			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506