

From: [Lucas Huck](#)
To: [Sara Folk](#)
Cc: [Dusty Pilkington](#)
Subject: FW: SE-17-00004, 2, Bowers and Dyer Wellheads
Date: Friday, March 31, 2017 11:43:35 AM

Can you make sure Dusty has what he needs to respond I need these approved asap.

Thanks,

Luke Huck, P.E.

County Engineer

Kittitas County Public Works

Phone 509-962-7523

Mobile 509-859-4965

Lucas.Huck@co.kittitas.wa.us

From: Mau, Russell E (DOH) [mailto:Russell.Mau@DOH.WA.GOV]
Sent: Friday, March 31, 2017 11:25 AM
To: Dusty Pilkington
Cc: Lucas Huck
Subject: RE: SE-17-00004, 2, Bowers and Dyer Wellheads

Mr. Pilkington:

Based on previous communications, these sites are for stockpiling road maintenance materials.

For the two figures, are these private wells or public water system wells? I only ask this question to determine if the State Department of Health has any regulatory authority. If they are private wells, then Kittitas County Health should be contacted.

As for the two provided maps, both show two well sites (i.e., two “circles” that I believe are 100-foot radius circles centered on wells in the vicinity of the sites that are proposed for stockpiling materials). For these maps, I have the following respective questions:

- For the graphic entitled “... Bowers Site ...”, the two wells are marked with yellow/orange circles and the site(s) for stockpiling are two abutting pink rectangles that are also cross-hatched? If “yes”, then I don’t see an issue with stockpiling materials.
- For the graphic entitled “Dyer Site ...”, the two wells are marked with red circles and then you show two areas enclosed by yellow/orange outline – are the yellow/orange areas the sites for stockpiling? If the site for stockpiling is the clear area to the northeast of the lower well site (assuming north is to the top of the graphic), then stockpiling in that area appears satisfactory – the ground slope appears to be toward the northeast on this map (away from the well) and the well has a vegetative buffer between it and the stockpiling area.

I await your input, thanks,

Russell E. Mau, PhD, PE
Regional Engineer
Department of Health, Office of Drinking Water
16201 East Indiana Avenue, Suite 1500, Spokane Valley, WA 99216
Desk: 509-329-2116
Fax: 509-329-2104
Russell.Mau@DOH.WA.GOV

Public Health - Always Working for a Safer and Healthier Washington

Visit our web site at www.doh.wa.gov/ehp/dw

From: Dusty Pilkington [<mailto:dusty.pilkington@co.kittitas.wa.us>]
Sent: Friday, March 31, 2017 8:45 AM
To: Mau, Russell E (DOH) <Russell.Mau@DOH.WA.GOV>
Cc: Lucas Huck <lucas.huck@co.kittitas.wa.us>
Subject: SE-17-00004, 2, Bowers and Dyer Wellheads

Mr. Mau,

Attached are two maps showing 100 foot buffers from wellheads near the Dyer and Bowers sites for the SEPA review on the materials storage. If DOH is satisfied, we can then issue the threshold determinations on these two sites. As seen on the maps, the work comes nowhere near the 100 foot radius around the Bowers site, and at the Dyer site, the buffer crosses into the vegetated area adjacent to the work location, but does not reach it.

Thank you,

Dusty Pilkington
Planner I
Kittitas County Community Development Services
411 N Ruby St # 4, Ellensburg, WA 98926
(509) -962-7079
dusty.pilkington@co.kittitas.wa.us

Notice: Email sent to Kittitas County may be subject to public disclosure as required by law

Notice: Email sent to Kittitas County may be subject to public disclosure as required by law