## **INSPECTION REPORT**

OWNER'S NAME: OZBOLT

**PERMIT NUMBER:** 2006-8422

DATE:		9/28/2015	TYPE:	Final
TIME STARTED:		4:41 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		20-14-02053-0017		
	handrails must return to wall or stairwell on ends			
	2. complete water heater/boiler install			
INSTRUCTIONS: complete above, call for re-inspection				
NEXT INSPECTION: re-inspect				
RE-IN	SPECTION FEE	DUE? NO YE	S	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
	QU	ESTIONS? PLEASE CONTACT THE INSP		
<u>iessica.contratto</u> @co.kittitas.wa.us  • INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 •				
		TION REQUEST LINE: <a href="https://www.co.kittl">www.co.kittl</a> 1 N. Ruby Street, Suite 2, Ellensburg,		