INSPECTION REPORT

PERMIT NUMBER:	BP-10-00078	OWNER'S NAME:	ROWLEY
DATE:	5/13/2015	TYPE:	Final
TIME STARTED:	11:44 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-15-07000-0025		
1. wrap post	s in garage with sheetrock		
2. provide fire separation at horizontal plumbing vent where encroaching in ceiling			
3. timer on fan ok			
4. water heater ok			
5. smoke/co detectors ok			
6. fireplace has been permitted			
7. office is no longer a sleeping room			
INSTRUCTIONS: complete fire separation in above addressed areas. Do not occupy structure before			
fin	al		
NEXT INSPECTION: re-inspect fire concretion for final			
re-inspect fire separation for final			
RE-INSPECTION FEE DUE? YES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 			