INSPECTION REPORT

TYPE:

OWNER'S NAME:

SCHMIDT

Jessica Contratto

Final

BP-13-00146

10/27/2014

PERMIT NUMBER:

DATE:

TIME STARTED:	12:06 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-19-32057-0003		
1. insta	II a CO detector outside o	f sleeping roo	oms
INSTRUCTIONS: complete above, bring in picture. Permit card will be finaled then			
NEXT INSPECTION	: N/A		
RE-INSPECTION FE	E DUE? NO YES	S	\$
IF RE	EQUIRED, RE-INSPECTION FEES MUST B	E PAID PRIOR TO SC	CHEDULING A RE-INSPECTION
C	QUESTIONS? PLEASE CONTACT THE INSP	ECTOR AT THE FOLL	OWING E-MAIL ADDRESS:
	jess	sica.contratto @c	o.kittitas.wa.us
	ECTION REQUEST LINE: www.co.kit 411 N. Ruby Street, Suite 2, Ellensburg, V		