## **INSPECTION REPORT**

PERMIT NUMBER:	BP-13-00197	OWNER'S NAME:	PAUL NW INVESTMENTS
DATE:	8/25/2014	TYPE:	Framing
TIME STARTED:	1:24 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-19051-0071		
1. Gas at	18# -ok		
2. H2O at 50#-ok			
3. DWV on stack- ok			
4. seal registers to floor			
INSTRUCTIONS: ok	to insulate		
NEXT INSPECTION: i	nsulation/fireplace		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
	TION REQUEST LINE: <a href="www.co.kitti">www.co.kitti</a> L N. Ruby Street, Suite 2, Ellensburg, V		