INSPECTION REPORT

PERMIT NUMBER:	BP-13-00197	OWNER'S NAME:	PAUL NW INV
DATE:	11/14/2014	TYPE:	Final
TIME STARTED:	11:34 AM	INSPECTOR:	Amber Green
MAP NUMBER:	20-15-19051-0071		
1. CO2/Smoke Detector in the vicinity of the master bedroom.			
2. Lid of mechanical closet to be drywalled.			
3. WSEC Compliance cert with blower door and duct leakage tests.			
4. Complete venting for tankless hot water heater.			
5. Final water/sewer letter from Suncadia.			
INSTRUCTIONS: Complete Above, then call for re-inspection.			
NEXT INSPECTION: Re-Final			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			