## **INSPECTION REPORT**

PERMIT NUMBER:	BP-13-00276	OWNER'S NAME:	SILVER FIR
DATE:	7/25/2014	TYPE:	Radiant heat
TIME STARTED:	10:01 AM	INSPECTOR:	Amber Green
MAP NUMBER:	22-11-09054-0059		
Entryway	Hydronics (100#/15min)	) - OK	
Entry foo	ting - OK		
Rear Por	ch post footings - OK		
INSTRUCTIONS: O	K TO POUR. Forward	compaction te	st results for rear backfill.
NEXT INSPECTION:	EXT SHEAR		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUI	ESTIONS? PLEASE CONTACT THE INSPE	ECTOR AT THE FOLLOW	/ING E-MAIL ADDRESS:
	amber.green	@co.ki	ttitas.wa.us
	TION REQUEST LINE: <a href="www.co.kitti">www.co.kitti</a> 1 N. Ruby Street Suite 2 Ellensburg W		<del></del>