INSPECTION REPORT

| PERMIT NUMBER: | BP-13-00276 | OWNER'S NAME: | SILVER FIR |
|---|--------------------------|---------------|--------------------|
| DATE: | 1/2/2015 | TYPE: | Stove or fireplace |
| TIME STARTED: | 12:59 PM | INSPECTOR: | Jessica Contratto |
| MAP NUMBER: | 22-11-09054-0059 | | |
| 1. install | ok | | |
| 2. pull ins | sulation away from chimr | ney at atttic | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| INSTRUCTIONS: complete above, ok to cover | | | |
| NEVT INSPECTION: | | | |
| NEXT INSPECTION: | | | |
| RE-INSPECTION FEE DUE? VES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: | | | |
| jessica.contratto @co.kittitas.wa.us | | | |
| • INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506 | | | |