## **INSPECTION REPORT**

OWNER'S NAME: DEFOOR

TYPE:

Insulation

PERMIT NUMBER: BP-13-00413

DATE:

1/4/2016

TIME STARTED:		3:01 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		19-17-35053-0001		
	1. Insulatio	n ok		
	2. Permit card not on site			
INSTRUCTIONS: ok to cover				
NEXT INSPECTION: final				
RE-INSPECTION FEE DUE? YES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
iessica.contratto @co.kittitas.wa.us				
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>				