INSPECTION REPORT

PERMIT NUMBER:	BP-13-00529	OWNER'S NAME:	CHATTIN
DATE:	9/25/2014	TYPE:	Final
TIME STARTED:	1:00 PM	INSPECTOR:	Amber Green
MAP NUMBER:	20-15-19050-0141		
Bollard mechanical protection in garage.			
2. Insulate water lines at water tank.			
3. Fireplace fire off.			
4. Tempered window at the base of the stairs.			
5. Blower door test results.			
6. Self closing door at the garage.			
7. Complete railing at stairs.			
INSTRUCTIONS: Complete Above, Call for Re-Inspection			
NEXT INSPECTION: Re-Final			
RE-INSPECTION FEE DUE? NO YES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506