INSPECTION REPORT

PERMIT NUMBER:	BP-13-00581	OWNER'S NAME:	WILLEM
DATE:	12/4/2014	TYPE:	Final
TIME STARTED:	12:18 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	16-19-03050-0001		
1 whole	house fan in laundry to b	ne on timer	
2. sanitary flooring needed in kitchen			
3. CO detector required outside bedrooms			
4. obtain access and sewer sign off on permit card			
5. provide install manual for fireplace			
6. I will check on what needs to be finished with fire separation			
7. sheetrock cover on attic access			
INSTRUCTIONS: complete above, call for re-inspection			
NEXT INSPECTION:	re-inspection		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			