## **INSPECTION REPORT**

PERMIT NUMBER:	BP-13-00703	OWNER'S NAME:	BERTEIG
DATE:	2/24/2015	TYPE:	Re-inspection
TIME STARTED:	11:51 AM	INSPECTOR:	Amber Green
MAP NUMBER:	19-16-02000-0007		
1. Correc	tions OK		
2. Maintain clearances to fireplace vent pipes at upper draftstop.			
INSTRUCTIONS: Ok	to Cover with Above.		
NEXT INSPECTION: F	inal		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>			