## **INSPECTION REPORT**

PERMIT NUMBER:	BP-13-00725	OWNER'S NAME:	GREER-STEINBACH
DATE:	9/30/2014	TYPE:	Framing
TIME STARTED:	2:10 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-20-03000-0007		
1. gas at	17#- ok		
2. fresh air to woodstove to be below level of firebox at termination per mechanical code			
3. see draftstop at duct at insulation			
INSTRUCTIONS: ok to insulate. see corrections then			
NEXT INSPECTION: i	nsulation		
RE-INSPECTION FEE	OUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
<ul> <li>INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694</li> </ul>			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506